#### SPECIFICATIONS

Type: 6-cylinder in-line SOHC 7-main hearings

Displacement 156 4cu in (2563cc) Horsepower: 122@ 5200rpm (SAE net)

Torque: 141ft - Ib @ 3600rpm (SAE net) Carburetor: Downdraft 2-barrel, automatic choke

Electrical System

Battery 12 volts 70 amp hr. 10. Electric clock

Manual: 4-speed, all synchromesh

Batios: 1st - 3 579: 2nd - 2 081: 3rd - 1 397: 4th - 1 000: 13. 3-position dome light. Reverse - 4.399 14 Collapsible steering column

Ratio: All Sedan and Hardton - 3 900: Wagon w/manual transmission - 3 900: Wagon/automatic transmission - 4 111

Type: Front - double wishbones, coil springs, anti-sway bar Rear - Sedan and Hardtop - coil springs; Wagon - leaf

Type: Recirculating ball, variable ratio Turning Diameter: 32 8 feet

Type: Power front disc, rear drum

Diameter Front Disc 10.5 in (8.68 in effective dia.)

Type: 4-ply rated tubeless, double white stripe

Size: 6.45×14 Dimensions, Weight and Capacities

Overall length: 175.4 inches (Hardtop & 4-door Sedan) 176.6 inches (Station Wagon)

Overall height: 4-door Sedan - 55 1 inches: Hardtop -54.7 inches: Station Wagon - 56.7 inches Curb weight: 2730 (4-door Sedan and Hardtop), 2795

(Wagon) add 20lbs for automatic transmission Fuel Tank capacity: 15.9 gallons (14.5 gallons - Wagon) Oil capacity: 5.5 quarts

Cooling system capacity: 11.4 quarts

Chassis/Body

The Toyota policy of continual improvement in design and manufacture requires that models, specifications, equipment and price be subject to change

### STANDARD FEATURES

2 6-cylinder SOHC engine 3 Double white string tires 4. Wheel covers

6. Power front disc/rear drum brakes

7. Tinted glass. 8 Nylon pile carnets 9 Reclining front bucket seats

11 Electric rear window defogger 12 Engine compartment light

15. Variable ratio steering.

16. Dual headlights. 18. Cigarette lighter 19 Ashtrays front and rear

20. Dual horns.

22. Instrument panel color coordinated with interior and exterior color

23. Adjustable front head restraints. 24. Padded dash.

25. Padded sun visors. 26. Inside rear view mirror breaks away on severe impact.

27. Lighted locking glove box. 28. 4-way hazard warning light

29. Tool kit and touch-up paint 30. Unit body construction.

31. Individually fused headlights

32 Energy absorbing bumpers 33. Lined trunk

34. Reversible keys. 35. Front and rear armrests.

36. Inside hood release 37. Front and rear seat belt retractors

38. Column mounted dimmer switch.

39. Package tray under dash. 40 Recessed door looks

41. Vinvl-trimmed brocade material on seats 42. Side door reinforcement beams

1. 3-speed automatic transmission. 2. Power steering. 3. Air conditioning.

4 AM/FM radio (Standard on hardton )

6. 8-track stereo.

5. AM radio. (Optional on sedans and wagons)

There are more than 900 Toyota dealers across the country. And ten service training centers are available for the training of their service people. There, the technicians work to become experts As for parts, nine computerized parts depots

located throughout the U.S. help to keep your dealer well stocked.

We can't make getting your car serviced enjoyable. But we're doing the best we can to insure that you get fast, professional service on











Mark II Hardtop. The most stylish of the most.

There's no hiding the fact that the Mark II Hardrop was designed to appeal to the eyes, as well as the pocketbook. The smooth flowing body lines are highlighted by a sloping rear deek that gives the Mark II Hardrop the look of a sporty fastback. Styling touches of bright trim, wheel covers and double-striped withweall tres add to the overall attractiveness. And in typical Toyota fashion,

these extra styling features are all standard.
Going along with its sporty appearance, the Mark II
Hardtop, like all Mark II models, comes with a spirited
156 Acu in six cylinder engine. The biggest engine you'll
find in any Toyota passenger car.
The Mark II Hardtop also offers a beautifully styled

interior. That can be proved by simply turning the page



# Inside the Hardtop.



As you can see the rich styling you saw on the outside has been carried to the inside as well. The automatic transmission and air conditioning are optional. AM/FM radio is standard on Hardtop only.

Lidded console storage box. Four speed synchromesh transmission. Beautifully illuminated instrument panel with electric clock. These are just some of the things that are standard on the Mark II.

Mark II Sedan. The most practical of the most.



Consider the problem. You want a car that's sporty and elegant enough that you'll feel good driving it. Yet you need a car that's big enough to hold the whole family, comfortably. Whether you'r edriving across town or across the country. Oh yes, you don't want to have to pay a fortune for it either. What you want is the Toyota Mark II four-door Sedan. It's designed for four-door convenience, yet retains the long, low, wide look of an elegant sporty car.
And not only can a family fit in the Mark II Sedan, the Mark II Sedan can fit in a family budget. Even though its the most Toyota, it still doesn't take a lot to buy it.

Or to run it.







Mark II Wagon. The most of the most.

car And that's exactly what it is

# Room for most everything.



The instrument panel, shown in the padded dash on the Mark II Sedan and Station Wagon, was designed so that everything is within easy reach. (The AM radio shown is optional.)



It's inside the Mark II where you spend most of your time. Here you'll find foam padded reclining front bucket seats, wall-to-wall carpeting and lots of room ...to make living quieter and easier.



The door locking buttons on the Mark II Sedans and Wagons have been designed to help foil the prying fingers of children. The plunger type lock is recessed within a surrounding well and must be lifted straight up to unlock.

With all that space inside you'll be surprised to know that the Mark II Sedan still has room enough for all this and more in the trunk

# The most Toyota is mostly standard.

As you can see by now, most of the things that you'd want on your new car and would expect to have to pay extra for are already standard equipment on the Mark II. equipment list.)



keeps fresh air flowing through your car



Each Mark II model has its own personality. For instance here is the difference between the Sedan taillights (on



manifold improves driveability when cold and helps The new fuel return system helps prevent vapor lock and percolation. To minimize power loss and reduce fan noise during high speed

precise and easy steering and the optional power

The most under the hood. Six cylinders. (The Mark IIs have a big 156 4 cu in six cylinder

engine.) The cylinder head is made of aluminum alloy

to reduce engine weight and improve heat dissination. The Mark II has an exhaust heated automatic choke

for quick warmups and an engine oil cooler to help

control oil temperature. The water-heated intake

and Sedan models have coil spring rear with telescopic shocks and well balanced.



the turn signals and dimmer switch, the ignition and the steering wheel lock button. The energy absorbing designed to collapse upon severe impact. A safety feature that's standard on all Toyota



There are a few options though that will give a personal Air conditioning is another option that a lot of people Adjustable heat and vent louvers allow you to determine touch to your new Mark II. Like this 8-track stereo feel they can't do without. And that's easy to the right ventilation for you. Standard equipment top) and our Hardtop lights (on the bottom). tape deck. Or the AM/FM radio. understand. of course.

With this new safety designed steering column lock you 3-point front seat belts are standard, of course. But a have to push a button before the ignition key can be removed. This is designed to prevent the steering wheel from locking accidentally

new warning light that is designed to alert the driver to fasten his belt when the engine starts and the parking brake is released is now standard, too.

The rear windows of all Mark IIs come with an electric defogger as standard equipment.

You might expect double-striped whitewall tires and wheel covers like these to cost extra. But they don't not on the Mark II.

